

# General Environmental Incident Summary

**Incident:** 9175

**Notice:** 7/31/2019 0500

**Occurred:** 7/29/2019 0900

**DEM Incident No:**

**No Further Action:** ☒

**Responsible Party:** Youngquist Brothers Oil & Gas

**County:** Williams

**Twp Rng Sec Qtr:** 154 101 14

**Lat Long + Method:** 48.16111 -103.64460 Interpolation from map

**Location Description:** Kum and Go, 1301 Bison Dr, Williston, ND 58801.

**Submitted By Info:** steven ritter  
Youngquist Brothers  
2682 138th Ave NW  
Alexander ND 58831

**Received By Info:**

**Contact Info:** Steven Ritter  
2682 138th Ave NW  
Alexamder ND 58831

**Affected Medium:** 03 - soil

**Near. Occupied Bldg:** 144 Feet

**Type of Incident:** Fuel spill at station pump

**Release Contained:** Yes

**Reported to NRC:** Unknown

**Contaminant:** diesel Fuel - clear #2

**Volume of Release:** 30 gallons

**Duration of Release:** 6 minutes

**Agriculture Related:** No

**EPA Extremely  
Hazardous Substance:** Unknown

**Number of Fatalities:** 0

**Number of Injuries:** 0

**Cause of Incident:**

Employees placed bar in the fuel pump handle since the automatic shut off handles were disengaged. Left pump and went into station for drinks, overflowed from truck onto the concrete at the fuel island, down the sidewalk and a small amount onto the soil adjacent to the pump island. No fuel spilled into the sewer drain on the road, or the retention pond.

**Risk Evaluation:**

N/A

**Potential Env. Impacts:**

N/A

**Action Taken/Planned:**

Spoke with Emergency Manager with clean up and reclamation company as well. Integrity environmental (Lewis Virgo) was on site on 7/30/19. Oil absorbent was picked up and disposed of, and 18" of soil near the stormwater pond was removed. The sidewalks and concrete near the gas station were cleaned with degreaser and hydrovac cleaned up the soil and water/cleaning products used. All soil and materials were disposed of by integrity environmental. Will provide our company with disposal receipts as well. Our company is Youngquist Brothers Oil & Gas, located at 2682 138th Ave NW, alexander, ND 58831.

**Wastes Disposal Location:**

Clean solutions LLC

**Other Agencies Involved:**

Local Law Enforcement, Local Emergency Manager

**Updates**

---

**Date:** 7/31/2019      **Status:** Reviewed - Follow-up Required

**Author:** Crowdus, Kory

**Notes:**

Release at gas station. Follow-up is required.

**Updated Volume:** None at the time of this update

---

**Date:** 8/13/2019      **Status:** Inspection

**Author:** DeVries, Taylor

**Notes:**

Inspection Date: 8/13/2019

Arrived on location at 1300. Floor dry has been placed over the spill. Both diesel pumps have floor dry by them. The spills do not cover a large area, maybe 2 feet by 4 feet. Return to location for another inspection to make sure gas station picks up floor dry.

Photos were taken and can be found in the report folder.

**Updated Volume:** None at the time of this update

---

**Date:** 9/5/2019      **Status:** Inspection

**Author:** DeVries, Taylor

**Notes:**

Inspection Date: 9/5/2019

The floor dry has been removed. No further follow-up is needed at this time.

Photos were taken and can be found in the report folder.

**Updated Volume:** None at the time of this update